

Consequently

$$\begin{bmatrix} \dot{I}_a \\ \dot{\omega} \end{bmatrix} = \begin{bmatrix} R_a/L_a & K_E/L_a \\ K_T/J_M + J_L & B/J_M + J_L \end{bmatrix} \cdot \begin{bmatrix} I_a \\ \omega \end{bmatrix} + \begin{bmatrix} -V_{arm}/L_a \\ \tau_f + \tau_{gr}/J_M + J_L \end{bmatrix}$$

- A linear system of two equations (differential)
- Q: can you write a transfer function from these equations?
- Q: can you transform the equations into a block diagram?

By Laplace-transforming

$$V_{arm}(s) = R_a I_a(s) + L_a I_a(s)s + \omega(s) K_E \Rightarrow I_a(s) = \frac{V_{arm}(s) - \omega(s) K_E}{R_a + L_a s}$$

$$\tau = K_T I_a$$


$$K_T \frac{V_{arm}(s) - \omega(s) K_E}{R_a + L_a s} = (J_M + J_L) \omega(s) s + B \omega(s) + \tau_f + \tau_{gr}$$

and finally

$$\frac{\omega(s)}{V_{arm}(s)} = \frac{K_T / L_a J_T}{s^2 + [(R_a J_T + L_a B) / L_a J_T]s + (K_T K_E + R_a B) / L_a J_T}$$

- Considering gravity and friction as additional inputs


Block diagram



Analysis tools

- Control: determine V_a so to move the motor as desired
- Root locus
- Frequency response


First block diagram



$$H_{open_loop} = \frac{A}{1+s\tau_a} \frac{K_m}{1+s\tau_m} \frac{K_p}{s}$$


Root locus

$$H_{open_loop} = \frac{A}{1+s\tau_a} \frac{K_m}{1+s\tau_m} \frac{K_p}{s} \quad K = AK_m K_p$$




RA 2007

Changing K



RA 2007

Let's add something second diagram



$$H_{open_loop} = \frac{AK_m(K_p + sK_g)}{(1 + s\tau_a)(1 + s\tau_m)s}$$


Analysis

$$H_{open_loop} = \frac{AK_m K_p (1 + s \frac{K_g}{K_p})}{(1 + s\tau_a)(1 + s\tau_m)s}$$


$$K = AK_m K_p$$

$$Z_{feedback} = \frac{K_g}{K_p}$$


Root locus (case 1)



Root locus (case 2)





Overall...




Error and performance

$$\vartheta = \frac{\vartheta_d}{s} \quad M(s) = \frac{K_T}{(R_a + sL_a)(B + sJ_T) + K_E K_T}$$

$\vartheta(s) = \frac{1}{s} \omega(s)$

 closed loop (position)


$\vartheta(s) = \frac{s}{1 + \frac{1}{s} \omega(s) K_p}$


$\omega(s) = \frac{\frac{A}{1+s\tau_a} M(s)}{1 + \frac{A}{1+s\tau_a} M(s) K_g}$

 closed loop (velocity)

finally

$$\lim_{s \rightarrow 0} sH(s) = \lim_{t \rightarrow \infty} h(t)$$

$$\Rightarrow \lim_{s \rightarrow 0} s \frac{\vartheta_d}{s} \vartheta(s) = \lim_{s \rightarrow 0} \frac{s - \frac{1}{s} \omega(s)}{1 + \frac{1}{s} \omega(s) K_p} = \frac{\vartheta_d}{K_p}$$

- For zero error K must be 1 or the control structure must be different

Same line of reasoning


$$\vartheta_{final} = -\frac{\tau_{gr} R_a}{A K_T K_p}$$

- Final value due to friction and gravity

$$\left| \frac{\tau_{gr} R_a}{A K_T K_p} \right| \leq \vartheta_{max} \Rightarrow K_p \geq \frac{\tau_{gr} R_a}{A K_T \vartheta_{max}}$$

$$K_{p\min} = \frac{\tau_{gr} R_a}{A K_T \vartheta_{max}}$$

PID controller




PID controller

- We now know why we need the proportional
- We also know why we need the derivative
- Finally, we add the integral
 - Integrates the error, in practice needs to be limited

Interpreting the PID

- Proportional: to go where required, linked to the steady-state error
- Derivative: damping
- Integral: to reduce the steady-state error


Global view



About the amplifiers

- Linear amplifiers
 - H type
 - T type
- PWM (switching) amplifiers


Let's consider the linear as a starting point



H-type

- The motor doesn't have a reference to ground (floating)
- It's difficult to get feedback signals (e.g. to measure the current flowing through the motor)

T-type



RA 2007


On the T-type

- Bipolar DC supply
- Dead band (around zero)
- Need to avoid simultaneous conduction
(short circuit)

Things not shown

- Transistor protection (currents flowing back from the motor)
- Power dissipation and heat sink
 - Cooling
- Sudden stop due to obstacles
 - High currents → current limits and timeouts


T-type



$$I_c \approx \frac{V_{cc}}{R_{transistor} + R_{motor}}$$

PWM amplifiers

$$P = V_{ce} I_c$$



PWM signal

$$P = V_{ce} I_c$$

- Transistors either “on” or “off”
 - When off, current is very low, little power too
 - When on, V is low, working point close to (or in) saturation, power dissipation is low

Comparison

- 12W for a 6A current using a switching amplifier
- 72W for a corresponding linear amplifier

Why does it work?



$$\frac{\omega(s)}{V_{arm}(s)} = \frac{K_T / L_a J_T}{s^2 + [(R_a J_T + L_a B) / L_a J_T]s + (K_T K_E + R_a B) / L_a J_T}$$

- In practice the motor transfer function is a low-pass filter


T_s with $f_s \gg f_E$ ($f_s > 100f_E$)

- Switching frequency must be high enough


PWM signal




Feedback in servo amplifiers



Operating characteristic




We've already seen this




$$\frac{\omega(s)}{V_{in}(s)} = \frac{K_T / L_a J_T}{s^2 + [(R_a J_T + L_a B) / L_a J_T]s + (K_T K_E + R_a B) / L_a J_T} \frac{A_v}{(1 + s\tau_a)}$$

Current feedback




RA 2007

Current feedback



RA 2007

Motor driven by a current amplifier



$$\frac{\omega(s)}{V_{in}(s)} = \frac{K_T A_i}{(sJ_T + B)(1 + s\tau_a)}$$